

Lofty's Loft - Pinfold Lane - Bridlington - East Yorkshire - YO16 5XS

01 MAY 1997

Product Service Bulletin

Issue date

29-04-97

Bulletin Number

197 / TSE

Subject

T17 Reserved Riser, closing loop

Status

Mandatory

Identification

The closing loop should be no longer than 2.5cm (1") see diagram

Background Service bulletin 3 ring release besitations reported from Kassel dropzone
Owners should contact their dealer or the manufacturer to have their
risers modified in accordance with the manufacturer's instruction.

Compliance date

31-09-1997

Distribution

Dealers / Clubs / B.P.A.

Note:

FURTHER USE. Nevertheless the call for modification should be done as soon as possible. In case of use before the modification is done, all users should be informed about the possibility of baving problems as stated under BACKGROUND.



