

Thomas Sports Equipment Limited
Pinfold Lane
Bridlington, East Yorkshire, England, YO16 5XS
Tel : 01262 678299 / Fax: 01262 602063

RECALL NOTICE

Issue date	28-05-97
Bulletin Number	297 / TSE
Subject	TSE T17 Reserved Riser
Status	Mandatory
Identification	ALL TYPE 17 REVERSED RISERS
Background	3 ring release hesitations reported
Service bulletin	Owners should contact their dealer or the manufacturer to have their risers modified or replaced by the manufacturer.
Compliance date	IMMEDIATE
Distribution	Dealers / Clubs / B.P.A.

Note:

Any rigs which have TSE T17 Reversed Risers are **GROUNDING FOR FURTHER USE**, until the test, as detailed below, has been performed. If you are satisfied that your risers are working correctly then you may continue to use them, however, if you have any difficulty in operating your release cable in conjunction with these risers please contact your Dealer or Thomas Sports Equipment immediately. Upon contacting your Dealer or Thomas Sports Equipment a replacement set of risers will be supplied. To receive your replacement risers, please send back your old risers with the serial number of your container, the replacement risers will be returned in the same day post.

The Test.

1. The harness should be hung from the top of the risers, so that the jumper who intends using the equipment, has his/her feet just above the ground.
2. There should be safety people either side of the person who is to cutaway, to prevent injury, should the jumper fall awkwardly.
3. A one handed 'Cutaway' must then be easily achieved.
4. As the predominant harness/container is likely to have soft housings, qualified personnel must ensure that the cutaway cable is re-routed correctly.
5. After the test has been completed, the equipment data card should be endorsed that the risers release correctly.

If there are any queries regarding this Notice please contact Thomas Sports Equipment on 01262 678299 or Fax 01262 602063.