



# SERVICE BULLETIN

<b>DATE:</b>	DEC 1, 1990	<b>SERVICE BULLETIN #</b>	1509	<b># OF PAGES:</b>	2
<b>SUBJECT:</b>	RSL LANYARD LENGTH- TALON/TELESIS/CLASSIC				
<b>STATUS:</b>	ADVISORY				

**IDENTIFICATION:** All Talon/Classic containers P/N 4111-( ). All Telesis containers P/N 4113-( ). RSL lanyards P/N 2811-(1) & 2811-(2).

**BACKGROUND:** In order to ensure the installation of the correct RSL lanyards on the above container systems, the attached table will allow identification of the proper RSL configurations.

**SERVICE BULLETIN:** If the RSL lanyard does not fit properly, check the length against the chart for proper mating/compatibility.

**COMPLIANCE DATE:** AT EACH REPACK.

**AUTHORITY:**

SANDY R. REID, PRESIDENT  
Rigging Innovations Inc.  
P O Box 1398, Romoland, CA 92585  
Telephone: 909-928-1438  
FAX: 909-928-1538

**DISTRIBUTION:**

- All Rigging Innovations Dealers.
- All Parachuting Publications.
- National Aero Clubs, Parachuting Section.
- Military Parachute Organizations.